


ಸಮೃದ್ಧಿ

SAMRUDHI GROUND WATER CONSULTANT

J P Park, Muthyala Nagar, Bangalore - 560 054

REPORT ON GROUND WATER INVESTIGATIONName: Providing borewell water pipelines water supply works at
Word No.13.

Address: _____

Location: Mallasandra colony School Topography Magnetic SoilSoil Type: Gravatic Soil Rock Type: hard rock**RECOMMENDATIONS**Dia of Bore well Bit : 6 1/2 Water Level : 2"Depth Recommended : 900 - 1100 Yield : 480 - 690 - 940Casing Pipe Required : 60 - 80 MS Aquifers : G.P.H. 2000PVC Outer Casing if Required: — Point Location: ☒ ☐ ☐ ☐Remarks: —

Rain Water Harvesting Compulsory

Note: The survey was carried out by this divining / Geophysical method of Surveying is with our good Knowledge
and experience, However no guarantee of Water will be given

Mr. Bharath Raj


ಸಮೃದ್ಧಿ

SAMRUDHI GROUND WATER CONSULTANT

J P Park, Muthyala Nagar, Bangalore - 560 054

REPORT ON GROUND WATER INVESTIGATIONName : Providing borewell water pipe lines water supply works at
ward no.13.

Address : _____

Location : Near Attilakkamma Temple Topography Magenetic SoilSoil Type : Gravetic Soil Rock Type : hard rock**RECOMMENDATIONS**Dia of Bore well Bit : 6 1/2 Water Level : 2"Depth Recommended : 900 - 1100 Yield : 480 - 690 - 920Casing Pipe Required : 60.80MS Aquifers : G.P.H. 2000PVC Outer Casing if Required : — Point Location : ☒ ☐ ☐ ☐

Remarks : _____

Rain Water Harvesting Compulsory

Note : The survey was carried out by this divining / Geophysical method of Surveying is with our good Knowledge and experience, However no guarantee of Water will be given

for Samrudhi Ground Water Consultant

Mr. Bharath Raj

ಸಮೃದ್ಧಿ

SAMRUDHI GROUND WATER CONSULTANT

J P Park, Muthyala Nagar, Bangalore - 560 054


REPORT ON GROUND WATER INVESTIGATION

Name : Providing borewell water pipe lines Water Supply works
at Word No. 13.

Address: _____

Location: BHEL mini colony Main Road Topography Magenetic Soil

Soil Type: Gravatic Soil Rock Type: hard rocks.



RECOMMENDATIONS

Dia of Bore well Bit : 6 1/2 Water Level : 2"

Depth Recommended : 900-1100 Yield : 490-680-900

Casing Pipe Required : 60-80 MS Aquifers : G.P.H. 2000

PVC Outer Casing if Required: _____ Point Location: ☒ ☐ ☐ ☐

Remarks: _____

Rain Water Harvesting Compulsory

Note : The survey was carried out by this divining / Geophysical method of Surveying is with our good Knowledge and experience, However no guarantee of Water will be given

AS T

Mr. Bharath Raj


ಸಮೃದ್ಧಿ

SAMRUDHI GROUND WATER CONSULTANT

J P Park, Muthyala Nagar, Bangalore - 560 054

REPORT ON GROUND WATER INVESTIGATIONName : Providing borewell water pipe lines water supply works
at ward NO.13.

Address : _____

Location : Ravindra Nagara Topography Magnetic SoilSoil Type : Gravaliic Soil Rock Type : hard rock**RECOMMENDATIONS**Dia of Bore well Bit : 6 1/2 Water Level : 2"Depth Recommended : 900 - 1100 Yield : 490 - 680 - 920Casing Pipe Required : 60 - 80 MS Aquifers : G. P. H. 2000PVC Outer Casing if Required : - Point Location : ☒ ☐ ☐ ☐

Remarks : _____

Rain Water Harvesting Compulsory

Note : The survey was carried out by this divining / Geophysical method of Surveying is with our good Knowledge and experience, However no guarantee of Water will be given

Mr. Bharath Raj